


**FIG. 1**  
PRIOR ART

$$\mathbf{t}_l = [01-1-111-11-11-1-1-1-1-111-1-11-11-111110\dots \\ \dots 011-1-111-11-1111111-1-111-11-11111]$$


**FIG. 2**  
PRIOR ART



**FIG. 3**  
PRIOR ART

$$\begin{aligned} \mathbf{t}_7^1 &= [0 \ 1 \ 0 \ 0 \ 1 \ 0 \ 0 \ 1 \ 0 \ 0 \ -1 \ 0 \ 0 \ -1 \ 0 \ \dots] \\ \mathbf{t}_7^2 &= [0 \ 0 \ -1 \ 0 \ 0 \ 1 \ 0 \ 0 \ -1 \ 0 \ 0 \ -1 \ 0 \ 0 \ -1 \ \dots] \\ \mathbf{t}_7^3 &= [0 \ 0 \ 0 \ -1 \ 0 \ 0 \ -1 \ 0 \ 0 \ 1 \ 0 \ 0 \ -1 \ 0 \ 0 \ \dots] \end{aligned}$$

**FIG. 4**



**FIG. 5**

600




FIG. 6

$$\begin{matrix} T_x^1 \\ T_x^2 \\ T_x^3 \end{matrix} \begin{bmatrix} 1 & 0 & 0 & 1 & 0 & 0 & 1 & \dots & 0 & 0 & 1 \\ 0 & 1 & 0 & 0 & 1 & 0 & 0 & \dots & 1 & 0 & 0 \\ 0 & 0 & 1 & 0 & 0 & 1 & 0 & \dots & 0 & 1 & 0 \end{bmatrix}$$

$$R_x \begin{bmatrix} H_1^1 & H_2^2 & H_3^3 & H_4^1 & H_5^2 & H_6^3 & H_7^1 & \dots & H_{50}^2 & H_{51}^3 & H_{52}^1 \end{bmatrix}$$

FIG. 7

800



FIG. 8  
PRIOR ART

900




FIG. 9

$$\begin{matrix} T_x^1 \\ T_x^2 \end{matrix} \begin{bmatrix} 1 & 0 & 1 & 0 & 1 & 0 & 1 & \dots & 0 & 1 & 0 \\ 0 & 1 & 0 & 1 & 0 & 1 & 0 & \dots & 1 & 0 & 1 \end{bmatrix}$$

$$R_x^1 \begin{bmatrix} H_1^1 & 0 & 0 & H_4^2 & 0 & 0 & H_7^1 & \dots & 0 & 0 & H_{52}^2 \\ 0 & H_2^2 & 0 & 0 & H_5^1 & 0 & 0 & \dots & H_{50}^2 & 0 & 0 \\ 0 & 0 & H_3^1 & 0 & 0 & H_6^2 & 0 & \dots & 0 & H_{51}^1 & 0 \end{bmatrix}$$

FIG. 10

1100





FIG. 11



**FIG. 12**